

Message

From: Beslow, Mike [beslow.mike@epa.gov]
Sent: 5/30/2017 4:25:10 PM
To: Dixit, Naeha [dixit.naeha@epa.gov]
Subject: FW: ArcelorMittal Outfall report, 5/28/17
Attachments: FROM IHWPQ204@arcelormittal.com.pdf; 910.jpg; 001.jpg

Flag: Follow up

FYI – Sunday:

From: Barnett, Thomas R [mailto:Thomas.Barnett@arcelormittal.com]
Sent: Sunday, May 28, 2017 4:35 PM
To: Fitzgerald, Sean F MST1 <Sean.F.Fitzgerald@uscg.mil>; Beslow, Mike <beslow.mike@epa.gov>
Cc: nream@idem.IN.gov; Lurtz, Kevin <Kevin.Lurtz@arcelormittal.com>; Benoit, Simonne T <Simonne.Benoit@arcelormittal.com>; Doyle, Kevin <Kevin.Doyle@arcelormittal.com>
Subject: ArcelorMittal Outfall report, 5/28/17

Outer hard boom and soft boom has become detached at Outfall 001, a soft boom is still in place outside the weir. Kenny Manta onsite today and yesterday working the outfall inside the weir. They will be out again on Memorial day, will get National out as soon as possible to reattach outer hard boom and the one soft boom (this requires a boat).